

Date	Site	Gender	Age Group	Activity	Probable Main Agent	Voltage
1 st March 2016	Outdoor Farm	Male	Adult 25-50 (32)	Work Tree-Felling	Wet rope touched OH Line	20 kV
June-2015	Outdoor Garden	Male	Adult Over 50 (59)	Non-Work (Gardening)	Ladder touching OH Line	20kV
22 nd Sep2014	Indoor Electrical Sub-Station	Male	Adult Over 50 (54)	Work	Switchgear	38 kV
25 th August 2014	House	Male	Adult Over 50	Non-Work	Heater	LV
18-Jul-2013	Farm Outhouse	Male	14	Workplace	Power Hose & Cable Reel	LV
16-Jan-2013	Electrical Sub-Station	Male	Adult < 25	Work	38 kV Bus-Bar	38 kV
2012	House	Male		Non-Work	Electric-Heater	LV
24-Sep-2012	Countryside	Male	Adult Over 50 (58)	Work	Overhead Line	LV
13th March 2012	Construction Site	Male	Adult 25-50	Work	Overhead Line	20 kV
10 th Dec-11	Household	Male	Adult 25-50		Electric Shower	LV
24-Sep-11	Workshop	Male	Adult Over 50	Work	Cable Lead-Compressor	LV
15-Jul-2010	Mobile home park	Male	Adult 25-50	Non-Work	Mobile home became live	LV
29-May-10	Domestic Garage	Male		Non-Work	Possibly self inflicted	LV
19-May-10	Hedgerow	Male	Adult 25-50	Work	Pole saw made contact with overhead line	20kV
01-Feb-10	Indoor 10kV substation	Male	Adult 25-50	Non-Work	Energised Cable and hack saw.	10kV

Date	Site	Gender	Age Group	Activity	Probable Main Agent	Voltage
09-Oct-09	Landscaped Garden	Male	Adult 25-50	Work	Flexible Cable	LV
25-Jul-08	Construction Site/Farm	Male	Adult 25-50	Work	Truck Mounted Crane	10 kV
09-Sep-07	Private housing/Apartment development	Male	Under 12	Non Work	Vandalised Lamp-post	LV
23-Apr-07	Construction	Male	Adult < 25	Work	Floating Concrete	10 kV
Dec-05	Construction	Male	Adult 25-50	Work	Concrete Conveyor	10kV Line
Oct-05	Construction	Male	Adult 25-50	Work	Metal Stay	20 kV
Oct-05	Construction	Male	Adult < 25	Work	Installing Concrete Slab	10kV
2005	Industrial	Male	Adult 25-50	Work	Welder in Hospital	LV
2005	Household	Male	Adult 25-50	Non Work	Washing Machine	LV
Nov-04	Farm	Male	Adult 25-50	Non Work	Lighting Tower	20kV Line
Nov-04	Farm	Male	Adult 25-50	Non Work	Lighting Tower	20 kV
Nov-04	Construction	Male	Adult 25-50	Work	Guttering	10 kV
Jun-04	Farm	Male	Adult < 25	Work	Silage Harvester	10kV Line
13-Jan-04	Yard	Male	Adult 25-50	Work	Truck Mounted Crane	20kV Line
2003	Industrial	Male	Adult 25-50	Work	Exploding Circuit Breaker	10 kV
2003	Industrial	Male	Adult 25-50	Work	Exploding Circuit Breaker	10 kV

Date	Site	Gender	Age Group	Activity	Probable Main Agent	Voltage
2003	Construction	Male	Adult < 25	Work	Concrete Chute	10 kV
2002	Industrial	Male	Adult 25-50	Work	Crane moving Welder	10 kV
2002	Countryside	Male	Adult 25-50	Work	Cutting Timber	20 kV
2002	Garden	Male	Adult 25-50	Non Work	Secateurs cut cable	LV
2002	Utility Substation	Male	Under 12	Non Work	Child Climbed into Sub	10 kV
Nov-01	Construction	Male	Adult 25-50	Work	Tipping Tarmacadam	10 kV
Oct-01	Farm	Male	Adult < 25	Work	Live Parts in a Poultry shed	LV
Oct-01	Construction	Male	Adult 25-50	Work	Truck Mounted Crane	38 kV
Jun-01	Industrial	Male	Adult 25-50	Work	Plumbing in Kitchen	LV
Dec-00	Construction	Male	Adult < 25	Work	Lighting POD	LV
Dec-00	Construction	Male	Adult 25-50	Work	Lighting POD	LV
Dec-00	Farmland	Female	Adult Over 50	Non Work	Fallen ESB Line	10 kV
Nov-00	ESB Network	Male	Adult 25-50	Work	ESB Technician Working	10 kV
Sep-00	Household	Male	Adult < 25	Non Work	Changing Bulb	LV
Aug-00	Household	Male	Under 12	Non Work	Toddler-Nail in Socket	LV
Jun-00	Milking Parlour	Male	Adult 25-50	Work	Milking Machine Became Live	LV

Date	Site	Gender	Age Group	Activity	Probable Main Agent	Voltage
Sep-00	Industrial	Male	Adult 25-50	Work	Electrician Killed by Metalwork	LV
Jan-00	Basement of Apartment block	Male	Adult < 25	Work	Delivery Person Copper Pipes on Broken Light Switch	LV
14-Dec-99	Utility substation	Male	Adult < 25	Non Work	Man Gained Access to Substation	110kV
07-Sep-99	Construction	Male	Adult 25-50	Work	Concrete Conveyor	10 kV
03-Aug-99	Industrial	Male	Adult 25-50	Work	Elec. Craftsman working on 3 phase panel	LV
19-Nov-98	Industrial	Male	Adult 25-50	Work	Elec. Craftsman working on 3 phase Motor	LV
20-Oct-98	Railway	Male	Adult 25-50	Non Work	Man on Dart Powerline	1500 VDC
01-Oct-98	Household	Male	Adult 25-50	Non Work	Working in Radio Hut	LV
04-Jun-98	Household	Male	Teenager	Non work	Having a shower	LV
01-May-98	Farm	Male	Teenager	Work	Mains on Electric Fence	LV
21-Aug-97	Farm	Male	Adult < 25	Work	Power Washer in Piggery	LV
04-Jul-97	Farm	Male	Adult < 25	Work	Welding in a Shed	LV
01-Mar-97	Construction	Male	Adult < 25	Work	Roofer Hit Line	10 kV
18-Nov-96	Halting site	Male	Adult Over 50	Work	Truck Mounted Crane	10 kV
16-Oct-96	Construction	Male	Adult 25-50	Work	Tipper Truck Driver stepping off truck	10kV

Date	Site	Gender	Age Group	Activity	Probable Main Agent	Voltage
06-Jun-96	Construction	Male	Adult 25-50	Work	Concrete Conveyor	10 kV
23-Mar-96	Industrial	Male	Teenager	Work	Teenager in Contact with Wire slung on 10 kV line	10kV
23-Jan-96	Household	Female	Adult < 25	Non Work	Woman Having Shower	LV
1995	Household	Male	Adult Over 50	Non Work	Contact with Bare Conductors in Socket	LV
15-Aug-95	Sports field	Male	Adult 25-50	Work	Portable Scaffold on Sports Pitch	10 kV
12-Apr-95	Countryside	Male	Adult < 25	Work	Truck Tipping	10 kV