

Date	Site	Gender	Age Group	Activity	Probable Main Agent	Voltage
29 May 2024	Waste Water Treatment Plant	Male	Adult 50-60	Maintenance	Exposed Live Parts	400 V
5 Oct 2023	House	Male	Adult 50-60	Plumbing	Metal became live	230 V
07/10/2017 (died on the 19th Oct)	Restaurant	Male	Adult Over 50 (56)	Catering	Cleaning in Restaurant. Accessible part became live.	230 V
1st March 2016	Outdoor Farm	Male	Adult 25-50 (32)	Tree-Felling	- Wet rope touched OH Line	20 kV
22 <sup>nd</sup> Sep2014	Indoor Electrical Sub-Station	Male	Adult Over 50 (54)	Electrical Maintenance	Switchgear	38 kV
18-Jul-2013	Farm Outhouse	Male	14	Farming	Power Hose & Cable Reel	LV
16-Jan-2013	Electrical Sub-Station	Male	Adult < 25	Electrical Maintenance	38 kV Bus-Bar	38 kV
24-Sep-2012	Countryside	Male	Adult Over 50 (58)	Work	Overhead Line	LV
13th March 2012	Construction Site	Male	Adult 25-50	Building	Overhead Line	20 kV
24-Sep-11	Workshop	Male	Adult Over 50	Garage Work	Cable Lead-Compressor	LV
19-May-10	Hedgerow	Male	Adult 25-50	Tree Maintenance	Pole saw made contact with overhead line	20kV
09-Oct-09	Landscaped Garden	Male	Adult 25-50	Gardening	Flexible Cable	LV

Date	Site	Gender	Age Group	Activity	Probable Main Agent	Voltage
25-Jul-08	Construction Site/Farm	Male	Adult 25-50	Delivery	Truck Mounted Crane	10 kV
23-Apr-07	Construction	Male	Adult < 25	Building	Floating Concrete	10 kV
Dec-05	Construction	Male	Adult 25-50	Building	Concrete Conveyor	10kV Line
Oct-05	Construction	Male	Adult 25-50	Work	Metal Stay	20 kV
Oct-05	Construction	Male	Adult < 25	Work	Installing Concrete Slab	10kV
2005	Industrial	Male	Adult 25-50	Maintenance	Welder in Hospital	LV
Nov-04	Construction	Male	Adult 25-50	Building	Guttering	10 kV
Jun-04	Farm	Male	Adult < 25	Farming	Silage Harvester	10kV Line
13-Jan-04	Yard	Male	Adult 25-50	Work	Truck Mounted Crane	20kV Line
2003	Industrial	Male	Adult 25-50	Maintenance	Exploding Circuit Breaker	10 kV
2003	Industrial	Male	Adult 25-50	Maintenance	Exploding Circuit Breaker	10 kV
2003	Construction	Male	Adult < 25	Building	Concrete Chute	10 kV
2002	Industrial	Male	Adult 25-50	Work	Crane moving Welder	10 kV
2002	Countryside	Male	Adult 25-50	Work	Cutting Timber	20 kV
Nov-01	Construction	Male	Adult 25-50	Road Work	Tipping Tarmacadam	10 kV
Oct-01	Farm	Male	Adult < 25	Work	Live Parts in a Poultry shed	LV
Oct-01	Construction	Male	Adult 25-50	Work	Truck Mounted Crane	38 kV

Date	Site	Gender	Age Group	Activity	Probable Main Agent	Voltage
Jun-01	Industrial	Male	Adult 25-50	Work	Plumbing in Kitchen	LV
Dec-00	Construction	Male	Adult < 25	Work	Lighting POD	LV
Dec-00	Construction	Male	Adult 25-50	Work	Lighting POD	LV
Nov-00	ESB Network	Male	Adult 25-50	Work	ESB Technician Working	10 kV
Jun-00	Milking Parlour	Male	Adult 25-50	Work	Milking Machine Became Live	LV
Sep-00	Industrial	Male	Adult 25-50	Work	Electrician Killed by Metalwork	LV
Jan-00	Basement of Apartment block	Male	Adult < 25	Work	Delivery Person Copper Pipes on Broken Light Switch	LV
07-Sep-99	Construction	Male	Adult 25-50	Work	Concrete Conveyor	10 kV
03-Aug-99	Industrial	Male	Adult 25-50	Work	Elec. Craftsman working on 3 phase panel	LV
19-Nov-98	Industrial	Male	Adult 25-50	Work	Elec. Craftsman working on 3 phase Motor	LV
01-May-98	Farm	Male	Teenager	Work	Mains on Electric Fence	LV
21-Aug-97	Farm	Male	Adult < 25	Work	Power Washer in Piggery	LV
04-Jul-97	Farm	Male	Adult < 25	Work	Welding in a Shed	LV
01-Mar-97	Construction	Male	Adult < 25	Work	Roofer Hit Line	10 kV
18-Nov-96	Halting site	Male	Adult Over 50	Work	Truck Mounted Crane	10 kV
16-Oct-96	Construction	Male	Adult 25-50	Work	Tipper Truck Driver stepping off truck	10kV

Date	Site	Gender	Age Group	Activity	Probable Main Agent	Voltage
06-Jun-96	Construction	Male	Adult 25-50	Work	Concrete Conveyor	10 kV
23-Mar-96	Industrial	Male	Teenager	Work	Teenager in Contact with Wire slung on 10 kV line	10kV
15-Aug-95	Sports field	Male	Adult 25-50	Work	Portable Scaffold on Sports Pitch	10 kV
12-Apr-95	Countryside	Male	Adult < 25	Work	Truck Tipping	10 kV